Material Safety Data Sheet

May be used to comply with OSHA's Hazard Communication Standard, 29 CFT 1910.1200. Standard must be consulted for specific requirements.



U.S. Department of LaborOccupational Safety and Health Administration (Non-Mandatory Form) Form Approved OMB No. 1218-0072

	IDENTITY (As Used on Label and List) QUICK-FILL™			Note: Blank Spaces are not permitted. If any item is not applicable, or no information is available, the space must be marked to indicate that.			
Section I							
Manufacturer's Name		Emergency Telephone Number					
JS Dental Manufacturing, Inc. Address (Number, Street, City, State, Zip Code	.\		203-438-8832				
196 North Salem Road	203-438-8832	Telephone Number for Information 203-438-8832					
Ridgefield, CT 06877	Date Prepared March 2001						
U.S.A.	Signature of Prepare	r (Optional)					
	lianta/Idantitu	Information					
Section II – Hazardous Ingred	nents/identity	iniormation		Other Limits			
Hazardous Components (Specific Chemical Ide	entity; Common Name	(s) OSHA PEL AC	CGIH TLV	Recommended	% (optional)		
Gutta Percha							
(Alpha phase Gutta Percha)							
Section III – Physical/Chemic	al Characteris	tics					
Section III – Physical/Chemic Boiling Point		tics Specific Gravity (H₂C) = 1)		2 55 - 2 60		
	N/A) = 1)		2.55 - 2.60		
Boiling Point Vapor Pressure (mm Hg.)		Specific Gravity (H ₂ C) = 1)		2.55 - 2.60 150° F		
Boiling Point	N/A	Specific Gravity (H₂C) = 1)				
Boiling Point Vapor Pressure (mm Hg.) Vapor Density (AIR = 1) Solubility in Water	N/A N/A	Specific Gravity (H ₂ C) Melting Point Evaporation Rate) = 1)		150° F		
Boiling Point Vapor Pressure (mm Hg.) Vapor Density (AIR = 1) Solubility in Water Negligible	N/A N/A	Specific Gravity (H ₂ C) Melting Point Evaporation Rate) = 1)		150° F		
Boiling Point Vapor Pressure (mm Hg.) Vapor Density (AIR = 1) Solubility in Water	N/A N/A	Specific Gravity (H ₂ C) Melting Point Evaporation Rate) = 1)		150° F		
Boiling Point Vapor Pressure (mm Hg.) Vapor Density (AIR = 1) Solubility in Water Negligible Appearance and Odor Burnt-Orange solid; Odorless	N/A N/A N/A	Specific Gravity (H ₂ C) Melting Point Evaporation Rate (Butyl Acetate = 1)) = 1)		150° F		
Boiling Point Vapor Pressure (mm Hg.) Vapor Density (AIR = 1) Solubility in Water Negligible Appearance and Odor Burnt-Orange solid; Odorless Section IV — Fire and Explosi Flash Point (Method Used)	N/A N/A N/A	Specific Gravity (H ₂ C) Melting Point Evaporation Rate (Butyl Acetate = 1) a Flammable Limits) = 1)	LEL N/A	150° F N/A		
Boiling Point Vapor Pressure (mm Hg.) Vapor Density (AIR = 1) Solubility in Water Negligible Appearance and Odor Burnt-Orange solid; Odorless Section IV — Fire and Explosi Flash Point (Method Used) N/A Extinguishing Media	N/A N/A N/A on Hazard Dat	Specific Gravity (H ₂ C) Melting Point Evaporation Rate (Butyl Acetate = 1) a Flammable Limits N/A) = 1)	LEL N/A	150° F N/A		
Boiling Point Vapor Pressure (mm Hg.) Vapor Density (AIR = 1) Solubility in Water Negligible Appearance and Odor Burnt-Orange solid; Odorless Section IV — Fire and Explosi Flash Point (Method Used) N/A Extinguishing Media Any media suitable for extinguis Special Fire Fighting Procedures	N/A N/A N/A on Hazard Dat	Specific Gravity (H ₂ C) Melting Point Evaporation Rate (Butyl Acetate = 1) a Flammable Limits N/A fire.) = 1)		150° F N/A		
Boiling Point Vapor Pressure (mm Hg.) Vapor Density (AIR = 1) Solubility in Water Negligible Appearance and Odor Burnt-Orange solid; Odorless Section IV — Fire and Explosi Flash Point (Method Used) N/A Extinguishing Media Any media suitable for extinguis	N/A N/A N/A on Hazard Dat	Specific Gravity (H ₂ C) Melting Point Evaporation Rate (Butyl Acetate = 1) a Flammable Limits N/A fire.) = 1)		150° F N/A		
Boiling Point Vapor Pressure (mm Hg.) Vapor Density (AIR = 1) Solubility in Water Negligible Appearance and Odor Burnt-Orange solid; Odorless Section IV — Fire and Explosi Flash Point (Method Used) N/A Extinguishing Media Any media suitable for extinguis Special Fire Fighting Procedures	N/A N/A N/A on Hazard Dat	Specific Gravity (H ₂ C) Melting Point Evaporation Rate (Butyl Acetate = 1) a Flammable Limits N/A fire.) = 1)		150° F N/A		

OSHA 174, Sept. 1985 (Reproduce locally)

Section V	Reactivity	Data	1			
Stability	Unstable		Conditions to Avoid Oxidizing Agents, heat	direct sunlight.		
	Stable	х				
Incompatibility (Materials to Avoid)					
Hazardous Deco	omposition or Bypro	ducts				
N/A Hazardous	us May Occur Conditions to Avoid					
Polymerization	Will Not Occur		N/A			
		Χ				
	l – Health Ha	zard Inhala			la grantina 2	
Route(s) of Entr		N		/ A	Ingestion? X	
	Acute and Chronic) n hazards					
Carcinogenicity:		NTP?		Monographs?	OSHA Regulated?	
Signs and Symp	otoms of Exposure					
140110						
Medical Condition	ons					
Generally Aggra	avated by Exposure	No	ne			
	First Aid December					
None None	First Aid Procedure	es				
			or Safe Handling and I	Jse		
	en in Case Material al requirement		eased or Spilled			
		-				
Waste Disposal						
Any ordii	nary disposal r	netno	a.			
Precautions to F	Be Taken in Handlin	g and S	Storing			
	a cool dark pla		avoid premature aging.			
None	ns					
	III – Control		sure			
Respiratory Prof	tection (Specify Typ	e)				
Ventilation	Local Exhaust N/A			Special N/A		
	Mechanical (Gene	eral)		Other N/A		
Protective Glove		action		rotection	od practice standards.	
Other Protective	red by good pro Clothing or Equipn		statiuatus. P	s required by 900	ou practice standards.	
None Work/Hygienic F	Practice					
As required by good practice standards.						