

# PARKELL<sub>day</sub>



155 Schmitt Blvd., PO Box 376, Farmingdale, NY 11735 Toll-Free 1-800-243-7446 Fax: (631) 249-1242  
Friday, June 23, 2000

SOLUTIONS FOR THE PROBLEM-SOLVING PROFESSIONAL

*Home | Trade Shows | International Distributors | How to Contact Us | MSDS Sheets*  
*Ordering | Products | What's New | Special Reports & Newsletters | Positions Available*

## SECTION I - PRODUCT IDENTIFICATION

<b>PRODUCT NAME:</b>	<b>BLU-MOUSSE CLASSIC &amp; SUPER-FAST</b>	<b>STOCK NO:</b>	<b>S436, S438 &amp; S457</b>
<b>DOT HAZARD LABEL:</b>	NA	<b>UN NUMBER:</b>	NA
<b>PROPER SHIPPING NAME:</b>	NA	<b>DATE PREPARED:</b>	02/15/00
<b>NFPA CODES:</b>	HEALTH - 0 FLAMMABILITY - 0 REACTIVITY - 0		

## SECTION II - HAZARDOUS INGREDIENTS/IDENTITY INFORMATION

<b>HAZARDOUS COMPONENTS</b>	<b>CAS NUMBER</b>	<b>PEL</b>	<b>TLV</b>	<b>%</b>
<b>NO HAZARDOUS INGREDIENTS</b>	NA	NA	NA	

## SECTION III - PHYSICAL & CHEMICAL CHARACTERISTICS

<b>BOILING POINT:</b>	NA	<b>SPECIFIC GRAVITY (H<sub>2</sub>O = 1):</b>	>1.00
<b>VAPOR PRESSURE:</b>	NA	<b>PERCENT VOLATILES:</b>	NA
<b>VAPOR DENSITY (Air = 1):</b>	NA	<b>EVAPORATION RATE (Butyl Acetate = 1):</b>	NA
<b>APPEARANCE AND ODOR:</b>	Light blue odorless paste.		

## SECTION IV - FIRE AND EXPLOSION HAZARD DATA

<b>FLASH POINT (TCC):</b>	NA	<b>UPPER:</b>	NA	<b>LOWER:</b>	NA
<b>EXTINGUISHER MEDIA:</b> Water, Carbon Dioxide, Dry chemical.					
<b>SPECIAL FIRE FIGHTING PROCEDURES:</b> None					
<b>UNUSUAL FIRE &amp; EXPLOSION HAZARDS:</b> None					

## SECTION V - REACTIVITY DATA (PHYSICAL HAZARDS)

<b>STABILITY:</b>	X	<b>STABLE</b>	<b>UNSTABLE</b>
<b>CONDITIONS TO AVOID:</b>	Avoid high heat.		
<b>INCOMPATIBILITY (Materials to avoid):</b>	Strong oxidizing agents, strong acids, & strong alkalis.		
<b>HAZARDOUS DECOMPOSITION PRODUCTS:</b>	None		
<b>HAZARDOUS POLYMERIZATION:</b>	MAY OCCUR	X	<b>WILL NOT OCCUR</b>
<b>CONDITIONS TO AVOID:</b>	None		

**SECTION VI - HEALTH HAZARD DATA**

PRIMARY ROUTE(S) OF ENTRY: EYES X SKIN INHALATION INGESTION

HEALTH HAZARDS (Acute & Chronic): May cause eye irritation upon contact.

SIGNS & SYMPTOMS OF EXPOSURE: NA

CARCINOGENECITY: No NTP? No IARC MONOGRAPHS? No OSHA?

EMERGENCY AND FIRST AID PROCEDURES:

INHALATION: NA

EYES: In case of eye contact with uncured materials, flush eyes with water.

SKIN: NA

INGESTION: NA

**SECTION VII - SPECIAL PRECAUTIONS AND SPILL OR LEAK PROCEDURES**

PRECAUTIONS TO BE TAKEN IN HANDLING & STORAGE: Shelf life prolonged if stored at ambient (72° - 74° F) temperature or below.

OTHER PRECAUTIONS: None

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED: Wipe up area with absorbent material and dispose in metal container. Be careful because residue is slippery.

WASTE DISPOSAL METHODS (Consult federal, state, and local regulations): Individual containers: dispose of as ordinary waste in accordance with local regulations. Case quantities: mix catalyst and base parts together, once they are fully cured you can dispose of in a sanitary landfill in accordance with local regulations.

**SECTION VIII - SPECIAL PROTECTION INFORMATION/CONTROL MEASURES**

RESPIRATORY PROTECTION: None required. required.

VENTILATION: None required.

PROTECTIVE GLOVES: None required.

EYE PROTECTION: None required.

OTHER PROTECTIVE CLOTHING OR EQUIPMENT: None required.

WORK/HYGIENIC PRACTICES: Wash hands before eating, drinking or smoking.

The information accumulated herein is believed to be accurate but is not warranted to be whether originating with the company or not. Recipients are advised to confirm in advance of need that the information is current, applicable, and suitable to their circumstances.

---

**Parkell**

155 Schmitt Blvd. Box 376, Farmingdale, NY 11735-0376  
(800)243-7446